

CORNER RECORD

COUNTY OF MADEIRA T. 85 R. 77E M.D.B. 1 MERIDIAN CALIF.

CORNER TYPE: GOV'T CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION --- DATE OF VISIT 4-15-75 19 75

SE. SECTION CORNER 73-8-77



23 / 74  
76 / 75


CORNER -- LEFT AS FOUND  FOUND & TAGGED  REESTABLISHED  OBLITERATED CORNER   
REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE & METHOD USED TO IDENTIFY OR REESTABLISH: FOUND 7" DIA. PIPE WITH COUPLING ON THE END 4 FT. ABOVE THE GROUND NEAR FENCE & HOUSE.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED:  
CUT 2" PIPE OFF SO 1' ABOVE GROUND & SET A 2" DIA. BRASS CAP ON PIPE.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NOS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_  
STATION \_\_\_\_\_ ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_  
EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)




2" PIPE WITH 2" BRASS CAP



SURVEYOR'S CERTIFICATE  
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 9-16 1975  
CHARLES VICTOR SIKORA

SIGNED: Charles Victor Sikora NO. 4126  
L.S. or R.C.E. No.: 234126



COUNTY SURVEYOR'S CERTIFICATE  
THE CORNER RECORD WAS RECEIVED 5-16 1975 EXAMINED AND FILED 6-9-75  
BY: Albert O. Barte  
TITLE: County Engineer

DOCUMENT No. 75-21-01  
STATEMENT ON BACK OF SHEET  
YES  NO