

CORNER RECORD


Document Number _____

City of _____

County of MADERA

California

Brief Legal Description NW COR. SEC 28 T8S R22E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

⊕
 NW COR SEC 28
 SEE REF. B

REFERENCE B: FOUND 2" IDIP (OPEN) UP 0.2' TIES: 1.7' E TO N-S FENCE
 N 85° W 18.10' TO 30d NAIL ON SP TO 23" BLUE OAK (ORIGINAL BT) SET K TAG } BRG & DISTANCE
 N 53° E 64.55' TO 30d NAIL ON N/S TO 24" BLUE OAK (NEW BT) } TO ⊙ CENTERS
 N 48° E 38.5' TO 22" BLUE OAK STUMP (UP 3.0') (ORIGINAL BT)

A description of the physical condition of the monument as found and as set or reset: _____

COPIED FROM ~~RS~~ RS 40/69

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined
 and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____