	ORNER RECOF	RD	
	. range 2:	EAST, M.D.B.&M	d. CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER CORNER ID TIFICATION - DATE OF VISIT: 106	RANCHO	. CONTROL	OTHER [
27 1/4 COR			
CORNER - LEFT AS FOUND [FOUND AND TAGGED [_	~ <u></u>
PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE IRON PIPE I			BLISH
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR F	ERPETUATED	3	
	ST SECO	OND TH	IIRD
STATIONS USED: NGS (USC & GS) STA	TE COUNTY	OTHER [STATE	ONSTATION
ONE ELEVATION	NORTHINGS (Y)	EAS	TINGS (X)
EXETCH: (INCLUDE REFERENCE TIE OR WITNESS POINT - ORIGINAL BEARING 7			
r			•
COPIED FROM OLD MADERA	COUNTY GOVERN	MENT MONUMEN	TS BOOK.

	JO RUE		
SURVEYOR'S CERTIFICATE THIS COPNER RECOPD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON	COUNTY SURVEYOR'S CERTIFICATE		
	AND EXAMINED AND FILED 19		
SIGNED:	ВУ:		
L.S. or R.C.E. No.	TITLE:		
SEAL	STATEMENT ON BACK OF SHEET: YES NO		

.....÷