


CORNER RECORD

COUNTY OF MADISA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M. D. B. & M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: JAN 19 86



N 1/4 cor. Sec. 30 1/2

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Fd Stone Mound 3'x2' 3 feet EAST of N/S fence.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
Set 1 1/2" ALUM. CAP in 3/4" IRON PIPE in Stone Mound, LS 4126 -

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

No suitable ties

Copied from RS 32/38

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.
SIGNED: _____
L.S. or R.C.E. No: _____
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____.
BY: _____
TITLE: _____
DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO