


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: Jan 19 86



SW cor. Sec. 30 1/2 22

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

F.D. 4" ALUM. CAP IN 4'x2' Stone Mound, LS 4509

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

Monument was originally accepted as Section Corner. It is really the witness monument at an original bearing of East 1/2 110 links from true corner.

Stamped the cap as witness monument. - ties are on record.

(Record data, 1878 G.L.O. survey by Glover)

Copied from RS 32/38

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 ____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 ____

AND EXAMINED AND FILED _____ 19 ____

BY: _____

TITLE: _____

DOCUMENT NO: _____ STATEMENT ON BACK OF SHEET: YES [] NO []