


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 _____



NORTHWEST CORNER, SECTION 31 8/22.

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [X] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found rock mound.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" x 30" Iron Pipe with 4" aluminum cap tagged L.S. 4509.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

- a.) 46 feet West to North-South fence.
- b.) South 105 feet to center line of creek.
- c.) N 2° 25' 11" W, 28.72 feet to PK nail & tag in a 15'x 8'x 7' granite outcrop.
- d.) S 76° 13' 45" E, 90.60 feet to a 30d nail on South side of a 36" White Oak.

*See SW cor
Sec. 30 8/22*

Copied from a Record of Survey, Vol. 28 Pg. 130 by Breadahl, L.S. 4509.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 _____

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____

AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No: _____ STATEMENT ON BACK OF SHEET: YES [] NO []