


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



W¹/₄ CORNER, SECTION 31, 8/22.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" x 30" Iron Pipe with 4" aluminum cap up 0.1' in cairn.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

- a) S 38° E, 22.92 feet to a 30d nail in a 20" Digger Pine.
- b) On a fence that runs in a NW/SE direction.
- c) South 31¹/₂ feet to a fence which is the R-O-W of Rd. 200.
- d) West 22 feet to the center line of a U.S.F.S. fire road.

Copied from a Record Of Survey, Vol. 28 Pg. 130 by Breadahl, L.S. 4509.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____

STATEMENT ON BACK OF SHEET: YES NO