CORNE	R RECORD
COUNTY OF MADERA TOWNSHIP SOUTH, R	vange 22 east, m.d.b.&m. california
CORNER TYPE: GOV'T. CORNER [MEANDER [RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT: MAY 20	<u>8</u> 19 <u>/9</u>
CORNER - LEFT AS FOUND TOUND AND TAGGED REE	CTARLITCHER ON THE CONTROL
PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND ME	
IRON PIPE	TO SULLITION REESTABLISH
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUAT	TED
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST	
STATIONS USED: NGS (USC & GS) STATE	COUNTY OTHER STATION STATION
ZONE ELEVATION NORT	HINGS (Y) FASTINGS (X)
WHITE DAK 19" DIA N 3	3°55'W 52.8"
	·
COPIED FROM OLD MADERA COUNT	V COVERNMENT MONITMENTS ROOK
	1
	AM ACTON
SURVEYOR'S CERTIFICATE	
THIS COPNER RECORD WAS PREPARED BY ME OR INDER MY	COUNTY SURVEYOR'S CERTIFICATE
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S	THE CORNER RECORD WAS RECEIVED 19
19	AND EXAMINED AND FILED 19.
SIGNED:	BY:
J.S. or R.C.E. No.	TITLE:

SEAL

DOCUMENT NO:
STATEMENT ON BACK OF SHEET: YES

ио 🔲