


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description S 1/4 COR. SEC 33, T8S, R22E



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- S 1/4 COR. SEC. 33 8/22
- TIES:
- S30° E 50.06' TO N&S IN FENCE POST
- N70° E 19.53' TO CHSILED 'X' IN ROCK
- SOUTH 67.15' TO N&S E/S BULL PINE TREE
- WEST 23' TO CTR. SMALL STREAM

COPIED FROM RS
BOOK 47 PAGE 98-100

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____