


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description SW COR SEC 33, T8S, R22E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SW COR. SEC. 33 9/22
 TIES:
 NORTH 5.20' TO N&S IN FENCE POST
 N60° E 14.70' TO N&S IN FENCE POST
 WEST 0.81' TO N&S IN 6" OAK TREE

COPIED FROM RS
BOOK 47 PAGE 98-100

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined and filed _____ 19____.

Signed _____ Title _____

County Surveyor's Comment _____