


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: May 19 81



West 1/4 corner section 35 8/22

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1 1/2" axle in fence line E-W This corner was set by county surveyor RUE on 3-15-27 in field book 129 pg. 8 from 2 orig. BT.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION
ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

.26' south to fence line E-W

7.0' NW to 5" W. Oak blazed

7.6' NE to 12" W. Oak blazed

Copied from Record of Survey for Frank Wyle
Surveyed by Steve Jones L.S. 4298 J & S Surveying

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

19

SIGNED:

L.S. or R.C.E. No:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 19

AND EXAMINED AND FILED 19

BY:

TITLE:

DOCUMENT No: STATEMENT ON BACK OF SHEET: YES [] NO []