

CORNER RECORD

COUNTY OF MADERA T. 8 S. R. 23 E. M.D.B & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT AUG. 12 & NOV. 19 19 77



NORTH 1/4 CORNER SECTION 7 8/23

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" IRON PIPE W/ UNION - UP 7"

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET FOUND PIPE WITH 3/4" x 30" IRON PIPE - L.S. 2737 - UP 8" IN STONE MOUND

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

95'± WEST OF C/L FOREST SERVICE ROAD
13" YELLOW PINE S. 88° 55' E 84.85' (ON W/S ROAD)
30" GOLDEN LIVE OAK (OLD BLAZE) S. 5° 06' E. 22.50'
5" SCRUB LIVE OAK N. 55° 31' W. 7.95'
4" SCRUB LIVE OAK N. 11° 13' E. 15.00' } I BLAZED

J.N. 77-104

F.B. 550/16

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON DEC. 15 19 78

SIGNED: William O. Gentry

L.S. or P.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES

NO