


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description NE CORNER SECTION 8, T. 8S, R. 24E.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____


COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SECTION CORNER
 T. 8S, R. 24E.
 FOUND 1 1/2" I.P. W/B.C.
 L.S. 2737 U.P.O. 7'
 DATED 9/4/1968
 TIES: 1.0' E TO N-S FENCE
 1.5' S TO FENCE WEST



A description of the N30°W 40.6' TO 24" DIGGER PINE AS FOUND AND AS SET OR RESET:
SNAG-LEANS SHARPLY SW
HAS K-TAG
NO ORIGINAL EVIDENCE FOUND

COPIED FROM RS 46/149

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined and filed _____ 19____.

Signed _____ Title _____

County Surveyor's Comment _____

