


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of MADERA, California

Brief Legal Description SE CORNER SEC. 8 T. 8 S., R. 24 E.



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SECTION CORNER  
 T. 8 S., R. 24 E.  
 FOUND 1 1/2" I.P.W/B.C. 43.2737  
 DATED 9/10/1968 UP 1.0'



TIES: S 0° W 101' TO A CHIMNEY (REMAINS OF OLD CABIN)  
 S 14° 34' E 41.81' TO 14" OAK STUMP UP 24" (CUT DOWN)  
 S 09° 01' W 111.12' TO 20" OAK STUMP UP 18" (CUT DOWN)  
 S 12° 04' W 79.14' TO 9" OAK STUMP UP 2" (CUT DOWN)  
 N 09° 12' W 58.72' TO 9" OAK STUMP UP 8" (CUT DOWN)  
 S 4° E 14.17' TO 8" BLUE OAK SET NAIL, SET K TAG  
 N 85° 53' E 1.58' TO Ⓞ OF 13" BLUE OAK, SET NAIL  
 S 71° 31' W 122.42' TO 36" BLUE OAK (BLAZE & AX MARKS ON S/S)

A description

NO ORIGINAL EVIDENCE FOUND

COPIED FROM RS 46/149

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_