


CORNER RECORD

COUNTY OF MADERA T. 9S R. 16E M. D. B. & M. MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT December 11, 1974



N.E. Corner of Section 26
 T.9S, R16E, M.D.B.&M.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Reset corner by ties.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

3/4" Iron Pipe tagged R.C.E. 18,489 0.3" Under

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (X) _____ EASTINGS (Y) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



<p>SURVEYOR'S CERTIFICATE</p> <p>THIS CORNER RECORD WAS PREPARED BY ME UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON <u>December 11, 1974</u></p> <p>SIGNED: <u>[Signature]</u> L.S. or R.C.E. No. <u>18,489</u></p>	<p>COUNTY SURVEYOR'S CERTIFICATE</p> <p>THE CORNER RECORD WAS RECEIVED <u>12/12</u> 19 <u>74</u> AND EXAMINED AND FILED <u>12/27</u> 19 <u>74</u> BY <u>[Signature]</u> TITLE: <u>County Engineer</u></p> <p>DOCUMENT No. <u>74-34-2</u></p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input checked="" type="checkbox"/></p>
--	--

