


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description SOUTH 1/4 CORNER OF SECTION 11 9/17



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

TIES:

0.59' S. OF SHINER IN 8" X 8" POST
38.1' NE OF TREE
39.3' NW OF TREE
20.6' SW OF TREE

A description of the physical condition of the monument as found and as set or reset: _____

SET 3/4" IRDN PIPE 30" LONG, 10" DOWN, TAGGED
R.C.E. 12,406.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment COPIED FROM PARCEL MAP NO. 3572
BOOK 44 PAGES 104-105.
SURVEYED BY R.W. GREENWOOD ASSOCIATES