	<del></del>	SOUTH, RANGE 17 EAST, M.D.B.GM. CALIFORNIA
CORNER TYPE:	GOV'T. CORNER 🗶 ME	ANDER RANCHO CONTROL OTHER
CORNER IDENTIFI	CATION - DATE OF VISIT:	19 70
<b>X</b>		
20	NORTH 1/4 CC	ORNER SECTION 20 9/17
	1.01.11. 17.1 00	STANDAR BEIGITOR 20 3/17
	1	
CORNER - LEFT A	S FOUND FOUND AND TAC	GGED REESTABLISHED OBLITERATED CORNER X REBUILT
PHYSICAL DESCRI	PTION OF CORNER FOUND; EV	IDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
•		
PHYSICAL DESCRI	PTION OF MONUMENTS REBUILT	T OR PERPETUATED
		D L.S. 2737 DOWN 9"
CALIFORNIA COOR	DINATE SYSTEM ORDER:	FIRST SECOND THIRD
STATIONS USED:	NGS (USC & GS)	STATE COUNTY OTHER STATION STATION
ZONE	ELEVATION	NORTHINGS (Y) EASTINGS (X)
mrray om	20.001	0 =17 ==4 ===
THEAST	39.00 <b>'</b> 46.35'	● IN FIG TREE
THEAST	34.00	<ul><li>● IN GUY POLE</li><li>● IN STOP SIGN</li></ul>
THWEST	50.30'	● IN STOP SIGN ● IN "NOT THRU ROAD" SIGN
THWEST	26.25'	O IN POWER POLE
THWES <b>T</b>	31.28'	O IN STOP & STREET SIGN
T	18.10	POWER LINE NORTH (OMIT 1st POLE)
T	12.60	POWER LINE SOUTH
TH	17.90'	POWER LINE EAST (2 POLES)
4		
01	DVEVOD'C GERTIEIGATE	
	IRVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE  IN DER MY THE CORNER RECORD WAS RECEIVED.
THIS CORNER RECO DIRECTION IN CON	RVEYOR'S CERTIFICATE ORD WAS PREPARED BY ME OR T FORMANCE WITH THE LAND SU	UNDER MY THE CORNER RECORD WAS RECEIVED 1 URVEYOR'S
THIS CORNER RECO	ORD WAS PREPARED BY ME OR	UNDER MY IRVEYOR'S  AND EXAMINED AND FILED  19
THIS CORNER RECO	ORD WAS PREPARED BY ME OR FORMANCE WITH THE LAND SU	UNDER MY THE CORNER RECORD WAS RECEIVED 1 PRVEYOR'S AND EXAMINED AND FILED 19
THIS CORNER RECO DIRECTION IN CON ACT ON	PRD WAS PREPARED BY ME OR FORMANCE WITH THE LAND SU	UNDER MY IRVEYOR'S  AND EXAMINED AND FILED  19