


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 9 SOUTH, RANGE 17 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 70



NORTHWEST CORNER SECTION 20 9/17

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RESET FROM TIES & MEASUREMENTS & LINE OF WEST LINE 20 9/17
RD 22 & AVE 27

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 2 1/2" IRON PIPE

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

NORTH	2638.24'	WEST 1/4 COR SEC 20 9/17	
NORTH	5276.48'	SOUTHWEST COR SEC 20 9/17	
SOUTHWEST	43.82'	⊙ IN "NOT THRU ROAD" SIGN POST	
NORTHWEST	32.28'	⊙ IN STOP SIGN	
SOUTHEAST	26.60'	⊙ IN STOP SIGN	
SOUTHEAST	22.78'	⊙ IN POWER POLE	
SOUTHEAST	25.78'	⊙ IN CORNER FENCE POST	
EAST	14.10'	POWER LINE SOUTH	
EAST	15.60'	POWER LINE NORTH	
NORTHEAST	49.68'	CENTERLINE VALVE	
NORTHEAST	54.35'	12" STANDPIPE	
SOUTH	16.85'	J P	

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
 STATEMENT ON BACK OF SHEET: YES NO