


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 9 SOUTH, RANGE 17 EAST; M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 70



NORTHWEST CORNER SECTION 21 9/17

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" IRON PIPE DOWN 14" WITH RDWD 3' WEST

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

SOUTHWEST	25.33'	⊙ IN POWER POLE
SOUTHWEST	23.60'	⊙ IN "NOT THRU ROAD" SIGN POST
SOUTHEAST	28.72'	3/4" IRON PIPE UP 7"
SOUTHEAST	29.90'	⊙ IN CORNER FENCE POST
NORTHEAST	41.97'	CENTERLINE VALVE
NORTHEAST	43.21'	CENTERLINE 8" STANDPIPE
SOUTHEAST	65.54'	⊙ IN TELEPHONE POLE
SOUTH	18.00'	POWER LINE EAST
WEST	17.90'	POWER LINE SOUTH
EAST	16.35'	TELEPHONE LINE SOUTH (OMIT 2nd P)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19_____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____

AND EXAMINED AND FILED _____ 19_____.

BY: _____

TITLE: _____

DOCUMENT No: _____

STATEMENT ON BACK OF SHEET: YES NO