

CORNER RECORD

COUNTY OF MADERA T. 9S. R. 18E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 15 19 76



NORTHWEST CORNER SECTION 7

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RESET FROM ORIGINAL BEARING TREE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 2" x 30" IRON PIPE - UP 15" IN STONE & EARTH MOUND - L.S. 2737

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

2.0' SOUTH OF STEEL FENCE POST - UP 5'
46" OAK N 28° 30' E. 221.76' (ORIGINAL B.T.)
3/4" I.P. - RCE 23841 - UP 6" S. 39° 45' 02" E. 22.95'
J.N. 76-145 F.B. 545 p. 49, 52

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 19 76.

SIGNED: William D. Gentry

L.S. or R.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6 19 76 AND EXAMINED AND FILED Dec. 13 19 76.

BY: A. Grate

TITLE: County Engineer

DOCUMENT No. 76-37-09

STATEMENT ON BACK OF SHEET

YES NO