


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 10E. M.D.B.# MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 16 19 76



WEST 1/4 CORNER SECTION 8

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RESET BY SINGLE PROPORTIONMENT

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1" x 35" IRON PIPE - UP 11" IN STONE & EARTH MOUND  
L.S. 2737

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GSI)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

18.5' SO. OF FENCE LINE W.  
104.7' E. OF FENCE LINE S.  
106.8' SE OF CORNER FENCE POST  
J.N. 76-145 F.B. 545 p. 52

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 19 76.

SIGNED: William D. Gentry

L.S. OR C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6 19 76 AND EXAMINED AND FILED DEC. 13 19 76.

BY: A. Grotz

TITLE: County Engineer

DOCUMENT No. 76-37-08

STATEMENT ON BACK OF SHEET

YES

NO