


CORNER RECORD

COUNTY OF MADERA T. S. 5. R. 18 E. M.D.B. 4 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 15 19 76



WEST 1/4 CORNER SECTION 17

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND HOLE OF 3" X 6" STAKE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1" X 30" IRON PIPE - L.S. 2737 - FLUSH IN SMALL STONE MOUND.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

18.6' SOUTH OF FENCE W.  
3.3' W. ✓ ✓ N.  
1.4' W. ✓ ✓ S.  
13.76' NW ✓ ○ IN SW COR. S. GATE POST.  
8.40' SW ✓ ✓ NW ✓ N. ✓ ✓  
J.N. 76-145 F.B. 545 p. 52

SURVEYOR'S CERTIFICATE  
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 18 19 76.

SIGNED: William D. Gentry  
L.S. or P.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE  
THE CORNER RECORD WAS RECEIVED DECEMBER 6 19 76 AND EXAMINED AND FILED Dec. 13 19 76.

BY: A. Photo  
TITLE: County Engineer  
DOCUMENT No. 76-37-10

STATEMENT ON BACK OF SHEET

YES  NO