


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 18E. MD.B.& MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 10, 19 76



WEST 1/4 CORNER SECTION 18

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1/2" IRON PIPE - STAMPED L.S. 2299 - UP 4"

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET WITH 1" x 30" IRON PIPE - L.S. 2737 - UP 3"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

0.4' W. OF FENCE So.  
ON LINE FENCE E. & W.  
18.5' ± E. OF FENCE No.  
49.8' SW OF WELL AT WINDMILL  
J.N. 76-145 F.B. 545/50

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 19 76.

SIGNED: William O. Gentry  
L.S. or REG. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6, 19 76 AND EXAMINED AND FILED Dec 13 19 76.

BY: A. Grote  
TITLE: County Engineer

DOCUMENT No. 76-37-72

STATEMENT ON BACK OF SHEET

YES  NO