

CORNER RECORD

COUNTY OF MADERA T. 9S R. 19E N.D. 134 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT JUNE 22 19 78



CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

SET BY SINGLE PROPORTION ON LINE BETWEEN W 1/4 CORNER SEC. 7 9/19 AND RE-ESTABLISHED NW CORNER SEC. 6 9/19.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 2" BRASS CAP FLUSH IN TOP NE CORNER 7'x6' GRANITE OUTCROP (6" BELOW SOIL LEVEL).

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

1.0' NORTH OF L.S. 2737 TAG IN SAME ROCK,
3.97' NW OF L.S. 2737 IN ANOTHER ROCK OUTCROP,
34.85' NORTH OF FENCE LINE EAST,
13.75' EAST OF FENCE LINE NORTH.

J.N. 78-090

F.B. 556/6

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JUNE 27 19 78.

SIGNED William O. Gentry

L.S. or R.C.E. No. 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED Sept 15 19 78.

BY: A. Brode

TITLE: County Engineer

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO