


CORNER RECORD

COUNTY OF MADERA T. 85 R. 23E M.D. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT B-11- 19 75



1/4 COR SEC 30, T8S, R23E, MDB&M

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1 1/2" IRON PIPE, NO I.D.; U.S.F.S. LOCATION TAG

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


PLACED 2" BRASS CAP WITH I.D., STAMPED L.S. 4126

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

BE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



CORNER SURVEYOR'S CERTIFICATE

CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON AUGUST 11 19 75

SIGNED: [Signature]
L.S. or R.C.E. No. 634126

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Aug. 11 19 75 AND EXAMINED AND FILED Aug. 11 19 75

BY: [Signature]
TITLE: County Engineer

DOCUMENT No. 75-26-63

STATEMENT ON BACK OF SHEET

YES NO