CORNER RECORD 23E MDBS Madera CALIFORNIA COUNTY OF MEANDER February 20,19 85 CORNER TYPE: GOYT. CORNER CONTROL [OTHER [X] CORNER IDENTIFICATION - DATE OF VISIT . West 1/16 corner of section 30 8/23. (NW corner of NE 4 NW4 of section 30 8/23) Common to sections 19 and 30 8/23. CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT TX PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH FOUND AND ACCEPTED: A 3" dia., octagonal brass cap, up 12" in a l'dia. Concreate slab flush with the ground. Corner position established by PG&E Co. (LS 2756) in 1971 by subdivision of section procedure. (Reference Record of Survey recorded in book 17 of maps at page 64. M.C.O.R. PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Built a rock mound 2½ 'x2½x½' high around monument. Set a metal post with Forest Service monument signs attached 4't NW of monument. THIRD [SECOND [CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [OTHER [STATIONS USED: NGS (USC & GS) STATE [COUNTY [STATION STATION . . NORTHINGS (Y) . EASTINGS (X) ELEVATION SKETCH: (Include reference tie or witness points, remarks and topo of area) CORNER TIES: CAP INSCRIPTION 1. A Black Oak, 23" dia., bears N 56° 45'E, 50.99'. 1/16 Cor 2. A forked White Oak, bears S 4° 26'E, 16.45'. 3. A Pine, 11" dia., bears S79° 58'W, 51.67'. LS 2756 4. A White Oak, 6" dia., bears N 11° 03'W, 67.30'. . Corner lies 11/2 Nw of a fence corner with fences running E'ly & S'ly. . Corner lies 180'± W of the centerline of road 222 (Auberry Road). . Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown. . Posted Forest Service Monument and Bearing Tree signs, on trees #1,#3, and #4. F.B. 31/66 Job No. 84-13 MY RECHUTE THIS CORNER YORS ACT AND EXAMINED DIRECTION IN DOCUMENT No.

STATEMENT ON BACK OF SHEET

L.S. WARRE