CORNER RECORD	
COUNTY OF Madera T. 85 R. 23E M.D.B.& MERIDIAN CALIFO CORNER TYPE: GOVT. CORNER MEANDER SANCHO CONTROL OTHER CONTROL CONTROL OTHER CONTROL MAY 5. 19.85	RNIA
The north corner of section 31 8/23. (Common to sections 30 and 31 8/23)	
CORNER — LEFT AS FOUND POUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT	
PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH	
FOUND AND ACCEPTED: A 1½" O.D. 1.P., up 12", with a 2" dia. brass cap stamped	
LS 4126. This monument is locally recognized and appears on several survey plats filed in the Madera County Records. It is accepted as the best available evidence of the original corner position.	
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
Left monument as found. Set a metal post with Forest Service Monument signs attached 4'± SW of the corner.	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION STATIO	
CORNER TIES CAP INSCRIPTION	
l. A P.K. nail and tag (LS 4689) in a rock 4'x2½'x2½' high T8S R23E bears N 8° 57' 12" E, 124.96'.	
2. A Digger Pine, 31.9" dia., bears N43° 29' E, 19.40'.	
3. A Black Oak, 25.9" dia, bears S31° 03'W, 44.76'.	
4. A P.K. nail and tag (LS 4689) in a rock 2'x2'x1' high, bears N 64° 48' 00'W, 36.47'.	
. Corner lies 7' West of a fence corner (fences run W'ly & NE'ly from fence corner).	
. Corner lies $52\frac{1}{2}$ West of the centerline of Auberry Road (road No. 222).	
. Bearings are to the center of trees at the base. Distance are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown.	
. Posted Forest Service Monument and Bearing Tree signs. V-5	
F.B. 33/09 Job No. 84-	13
SUMPLY SURVEYOR'S CERTIFICATE /	
THIS CORNER RECORD WAS PREPARED BY M GOLDER MY DIRECTION IN CONCORDANTEDWARD THE LUNG SAFETORS ACT ON 22 COHEN 19 STOLES SECURED AND FILED BY:	- 24

STATEMENT ON BACK OF SHEET

YES 🔲

№ 🗆