

CORNER RECORD

COUNTY OF Madera T. 8S R. 23E MD MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT 1-5-75 19__



5/4 COR SEC 31, T8S, R23E, MDBM

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


FOUND GLO BRASS CAP

56
1/4 531
1922


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



NOTE: Monument is in the open next to a rut-road in the field. There are no fences at this time



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 2-29-75 19__
SIGNED: [Signature]
L.S. or R.C.E. No.: 123456

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED 5-23 1975
AND EXAMINED AND FILED 5-29 1975
BY: A O Grote
TITLE: County Engineer
DOCUMENT No. 75-18-04

STATEMENT ON BACK OF SHEET

YES NO

SEAL