


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



WEST 1/4 corner Section 31 8/23

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1" IRON PIPE IN ROCK MOUND TAGGED L.S. 2737

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

CORNER IS 3.00' WEST OF FENCE NORTH-SOUTH FROM WHICH BEARS:

S 53° 34' E 39.92' 36" WHITE OAK
N 38° 43' E 18.04' Cross on s/s of 8'x10'x7' high Granite Boulder

COPIED FROM P.M. 1803 Rec 27/60 BY JONES L.S. 4298

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.
SIGNED: _____
L.S. or R.C.E. No: _____
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____.
BY: _____
TITLE: _____
DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES [] NO []