. CONVER RECORD	
CORNER RECORD  COUNTY OF Madera , 8 S , 23 E M.D.B. & M. MER	IDIAN CALIFORN
CORNER TYPE: GOYT. CORNER A MEANDER RANCHO CONTROL OTHER COMMER IDENTIFICATION — DATE OF VISIT April 23 19 85  The standard corner common to Sections 34 and 35 8/23.	WIRN CALIFORN
3, 5	
CORNER — LEFT AS FOUND TO FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBU	iirī 🗀
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH	•
Found and Accepted: A 2" O.D.I.P., up 6" with a 2½" dia. GLO brass ca corner. Found 2 original bearing trees per GLO fi William B. Kimmel, U.S. Cadastral Engineer, 1922.	
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
Left monument as found. Set a metal post with Forest Service monument 4'± SW of the corner.	signs attached
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION  ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)	STATION
	Cap Inscription
Corner Ties: Original Bearing Trees:	s c
1. A fallen Oak bears N 17° 06' E, 21.9'. (no nail)	·
2. An Oak, 31" dia. with a healed blaze, bears N 39° 26' W 64.9'.	<b>T8S</b> R23E
(no nail)	s 34 s 35
New Bearing Trees: 3. An Oak, 11.5" dia., bears N 45° 11' E, 37.99'.	1922
4. An Oak, 11.7" dia., bears S 3° 52' W, 46.79'.	
5. An Oak, 9.6" dia., bears N 25° 37' W, 23.20'.	
. Found a 1 $\frac{1}{2}$ ' dia. rock mound 3' $\pm$ N. of the corner as noted in GL of William B. Kimmel.	O field notes
. Bearings are to the center of trees at the base. Distances are horized and tag (stamped LS 4689) driven into the side center of the root crowise noted.	
. Posted Forest Service Monument and Bearing Tree signs.	Z-1
S AMO	F.B. 32/4 Job No. 84-1
THIS CORNER RECORD WAS PROJECT BY MARKED BY MARKED AND EXAMINED AND EX	CIRTIPICATE 19

LS 4689

STATEMENT ON BACK OF SHEET

ю □

YES 🔲