

PHONE 2-9315

ROSS & PRICE
CIVIL ENGINEERS AND LICENSED
LAND SURVEYORS
421 ROWELL BUILDING
FRESNO, CALIFORNIA

Sept. 19th. 1950

Dear Doug:-

Herewith what ties we have in section 11 7/21

1/4 Cor N.S. section 11

1" pipe in a rock mound
N.43-01 E. 172 feet to a 24" White oak
N.5°-01'W. 122 feet " "24" " "
S.81°-41'E. 133 feet " "40" " "

These trees were all blazed with a 6" Blaze 6/15/50

N.E. Cor Section 11 7/21

1 1/2" pipe in rock mound with bearing trees

N.W. Cor Section 11, 7/21

Found a split post in a rock mound One bearing tree
On fence line E. & W.
15.5 feet southwest of bearing tree

Center of section 11 7/21

Found old 1-1/2" pipe in small rock mound
52.3 S.E. of face of a 30" white oak blazed.
57.0 N.E. " " " " 30" " " "
36' W. " " " " 18" " " "

This corner is below the highway.

There is a railroad spike in the center of the
highway on the Line from the center to the 1/4 cor N.S.

Hope these are of use to you.

Sincerely

J. P. Ross