


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description C 1/4 COR SEC 27 6/22



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(19) CENTER 1/4 CORNER SEC 27 6/22
 DRILLED AND SET U.S.F.S. MON. IN ROCK MD. L.S. 4126
 FROM WHICH BEARS:

A description

18" P. ONE (TWIN) 5.00'E. 30.51
 26" Y. PINE N. 9° W. 26.85
 N. 53° 23' W. 16.96 TO L.S. 4126 TAG IN ROCK
 S. 48° W. 2.0 TO U.S.F.S. POST

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9