


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description SECTION 7 T7S R20E



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAVD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

PER RECORD OF SURVEY FOR MCKNIGHT RECORDED IN BOOK 50 PAGE 125

A description of the physical condition of the monument as found and as set or reset:

SET 5/8" STEEL BAR WITH PLASTIC CAP STAMPED LS 5339

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyor's Act on _____

Signed _____ P.L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____