CORNER RECORD

| OUNTER RECORD | |
|---|----------------------------------|
| COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE | GE 20 EAST, M.D.B.&M. CALIFORNIA |
| CORNER TYPE: GOV'T. CORNER [MEANDER [| RANCHO CONTROL OTHER |
| CORNER IDENTIFICATION - DATE OF VISIT: APRIL | 19 <u>_81</u> |
| North 4 corner of | section 22 7/20 |
| CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT | |
| PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH . | |
| | • |
| | |
| PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED | D |
| | |
| Set 3/4" I.P. tagged from bearing trees | RCE 12406, |
| CALIFORNIA COORDINATE SYSTEM ORDER: FIRST | SECOND THIRD |
| STATIONS USED: NGS (USC & GS) STATE C | COUNTY OTHER STATION STATION |
| ZONE ELEVATION NORTH | INGS (Y)EASTINGS (X) |
| SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA) | |
| TIES | |
| s 48° 30' W 120.8' d | of 48" Live Oak |
| N 15° W 62.5' 6 | of 24" White Oak |
| S 40° E 79.5' c | of 24" White Oak |
| | |
| Copied from P.M. 1918 for FOOTE & ALLEN | |
| Surveyed by Greenwood | RCE 12406 |
| | |
| | - |
| | |
| | |
| SURVEYOR'S CERTIFICATE | COUNTY SURVEYOR'S CERTIFICATE |
| THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S | THE CORNER RECORD WAS RECEIVED19 |
| ACT ON19 | AND EXAMINED AND FILED |
| SIGNED: | BY: |
| | T771.E+ |

DOCUMENT No:
STATEMENT ON BACK OF SHEET: YES

ио 🔲

L.S. or R.C.E. No: